
City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 1 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/19/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition :  Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S03SS_013MH	Test ID: S1032-022017	Notifications (Residents, Fire, 311) : Yes


**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/19/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition :  Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S03SS_013MH	Test ID: S1032-022017	Notifications (Residents, Fire, 311) : Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Catch Basin; Smoke: Heavy; Status: Public ROW

Landscape



#### Defect



ID



Location: N/A; Type: Other; Smoke: Light; Status: Public ROW

#### Landscape




## Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 3 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/19/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition :  Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S03SS_013MH	Test ID: S1032-022017	Notifications (Residents, Fire, 311) : Yes

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Catch Basin; Smoke: Heavy; Status: Public ROW


## Landscape



## **Defect**



ID



Location: N/A; Type: Storm Manhole; Smoke:

Light; Status: Public ROW

#### Landscape




## **Defect**



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 4 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/19/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet : _	Supervisor : John Daly
Manhole ID: S03SS 013MH	Test ID: S1032-022017	Notifications (Residents, Fire, 311) : Yes

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Catch Basin; Smoke: Medium; Status: Public ROW

#### Defect



# Landscape



## Defect

